

RECO			COPY NO.	PUB. DATE		LOCATION	· · ·		MASTI	ER	DATE RECEIVED	LOCATION		
			DISABOTO	ved for Re	lease	2003/0)5/14 :	ČΙΆ	RDF	78T	051่6ี1Äั่0ี01400 0 10021-	1 MAXIMUM	7	
CUT COP		0	DATE 1-73	CUT TO COPIES		DATE		COPI	ES DE	STROY	ED			
CUT			DATE	CUT TO COPIES		DATE								
CUT	TO	•	DATE	MASTER		DATE								
DATE					NUMBER OF COPIES		DATE			25051452 22 10045	NUMBER OF COPIES			
мо.	DAY	YR.	RECEIVED OR	ISSUED	REC	D ISS'D	BAL	MO.	DAY	YR.	RECEIVED OR ISSUED	REC D	ISS'D	BAL
8	12	68	Dest. Unit	¥41 - 47	7		7							
8	8	72	Dest #4	4-47			0	W	K	6				
					<u> </u>									
					ļ									
								-						
					-									
		+												
													<u> </u>	
					ļ									
			Annro	ved For Re	eas.	2003/)5/14 ·	CIA.	RDF	78T	 	1	<u> </u>	
τιτι X1	.e 	NPIC	PIR	77042	cast	Sept.	7966.	TS/	, ŠEV:	; ś. ጛ ' ` 	05161A001400010021-	2494	4	25X1
										d			•	20/

< 1	Approved For Release 2 pop 0 \$/E€RET -RDP78T05161A001400010021-1	

CIA IMAGERY ANALYSIS DIVISION

25X1


CIA/PIR-77042


KTANGNAN SHIPYARD

SHANGHAI, CHINA

25X1

- 1 -





	Approved For Release 2001/05/14/05/161A001400010021-1
	CIA/PIR-77042
LOC	TPYARD: KIANGNAN SHIPYARD SATION: SHANGHAI, CHINA COORDS: 31-12N 121-29E
	KEY TO ANNOTATIONS ON FIGURE 2
1.	KAIBOKAN Class PF hull (LOA approx 220'). This hull appeared to be stripped when it was seen on (see annotation 2, Figure 3, PIR-67221). Although the hull is still largely void of topside detail, the forward portion of the superstructure is now in place. This imagery equates to the original configuration of the KAIBOKAN I Class PF. A possible stack is also visible.
2.	Railroad Ferry (LOA approx 360'). See annotation 5, Figure 5,
3.	Unidentified possible passenger vessel (LOA approx 195').
4.	Floating crane alongside offshore wharf.
5•	Possible "R/W" Class SS (visible waterline length approx 250'). Rounded hull form and raised imagery on bow possibly equating to a sonar dome is visible. Light-toned imagery approximately in length can be seen on either side of the centerline of the submarine abaft the sail. A probable barge or camel is positioned between the offshore wharf and the submarine. A floating crane is operating outboard the submarine's por side.
6.	Unidentified probable merchant vessel in graving dock (LOA approx 205'). A small barge also occupies this graving dock. See annotation 4, Figure 4,
7.	Unoccupied graving dock.
8.	CASTLE Class OPF (LOA approx 250'). This vessel appears to have the conventional Chicom CASTLE Class configuration. Unidentified structures (probably temporary) are located on both the fantail and the foredeck of this ship. A probable CASTLE Class OPF was seen at Kiangnan Shipyard on (see annotation 17, PIR-67268). The vessel seen on that date appeared to have a different topside configuration abaft the superstructure.
	- 2 -

Approved For Release **700 P**/0**\$ FIGR ET**A-RDP78T05161A001400010021-1

25X²

SHIPYARD: KIANGNAN SHIPYARD LOCATION: SHANGHAI, CHINA GEO COORDS: 31-12N 121-29E KEY TO NUMEERED ANNOTATIONS ON FIGURE 3 1. Large unidentified merchant ship under construction on building way (visible extent of construction approx 425'). See annotation 10, Probable components for this ship can be seen about the shipyard. 2. Cylindrical object lying on its transverse axis (approximate maximum diameter 20'). See Figure 6, 3. Possible cylindrical object lying on its transverse axis (diameter is roughly 20'). A total of eight cylindrical objects (two of which were identified as possible submarine hull sections) were visible within the security screer surrounding the submarine building ways in See annotations 4-7, Figure 6, 4. Possible "R" Class SS under construction on building way (exact measure- ments of the SS cannot be determined - the length of the submarine including the weather sheds at each end is approximately 260'). This submarine appears to be in an advanced stage of construction - the sail appears in place and the deck is painted with a lengthwise dark stripe along the centerline. A small shed is positioned athwartships approximately 45 feet abaft the sail. See annotation 7, 5. Possible tug on building way (LOA approx 100'). It cannot be determined whether this vessel is under construction or repair. This way was formerly used for the construction of an "R" Class SS (see annotation 5, Figure 3, were seen on this way (see annotation 6,		CIA/PIR-77042
KEY TO NUMBERED ANNOTATIONS ON FIGURE 3 1. Large unidentified merchant ship under construction on building way (visible extent of construction approx 425'). See annotation 10, Probable components for this ship can be seen about the shipyard. 2. Cylindrical object lying on its transverse axis (approximate maximum diameter 20'). See Figure 6, 3. Possible cylindrical object lying on its transverse axis (diameter is roughly 20'). A total of eight cylindrical objects (two of which were identified as possible submarine hull sections) were visible within the security screer surrounding the submarine building ways in See annotations 4-7, Figure 6, 4. Possible "R" Class SS under construction on building way (exact measurements of the SS cannot be determined - the length of the submarine including the weather sheds at each end is approximately 260'). This submarine appears to be in an advanced stage of construction - the sail appears in place and the deck is painted with a lengthwise dark stripe along the centerline. A small shed is positioned athwartships approximately 45 feet abaft the sail. See annotation 7, 5. Possible tug on building way (LOA approx 100'). It cannot be determined whether this vessel is under construction or repair. This way was formerly used for the construction of an "R" Class SS (see annotation 5, Figure 3, small vessels were seen on this way (see annotation 6, small vessels were seen on this way (see annotation 5, small vessels)		
 Large unidentified merchant ship under construction on building way (visible extent of construction approx 425'). See annotation 10, Probable components for this ship can be seen about the shipyard. Cylindrical object lying on its transverse axis (approximate maximum diameter 20'). See Figure 6, Possible cylindrical object lying on its transverse axis (diameter is roughly 20'). A total of eight cylindrical objects (two of which were identified as possible submarine hull sections) were visible within the security screer surrounding the submarine building ways in See annotations 4-7, Figure 6, Possible "R" Class SS under construction on building way (exact measurements of the SS cannot be determined - the length of the submarine including the weather sheds at each end is approximately 260'). This submarine appears to be in an advanced stage of construction - the sail appears in place and the deck is painted with a lengthwise dark stripe along the centerline. A small shed is positioned athwartships approximately 45 feet abaft the sail. See annotation 7, Possible tug on building way (LOA approx 100'). It cannot be determined whether this vessel is under construction or repair. This way was formerly used for the construction of an "R" Class SS (see annotation 5, Figure 3, small vessels were seen on this way (see annotation 6, small probable fishing trawlers on ways (LOA of each roughly 85-90') 	LOC	CATION : SHANGHAI, CHINA
 (visible extent of construction approx 425'). See annotation 10, Probable components for this ship can be seen about the shipyard. 2. Cylindrical object lying on its transverse axis (approximate maximum diameter 20'). See Figure 6, 3. Possible cylindrical object lying on its transverse axis (diameter is roughly 20'). A total of eight cylindrical objects (two of which were identified as possible submarine hull sections) were visible within the security screer surrounding the submarine building ways in See annotations 4-7, Figure 6, 4. Possible "R" Class SS under construction on building way (exact measurements of the SS cannot be determined - the length of the submarine including the weather sheds at each end is approximately 260'). This submarine appears to be in an advanced stage of construction - the sail appears in place and the deck is painted with a lengthwise dark stripe along the centerline. A small shed is positioned athwartships approximately 45 feet abaft the sail. See annotation 7, 5. Possible tug on building way (LOA approx 100'). It cannot be determined whether this vessel is under construction or repair. This way was formerly used for the construction of an "R" Class SS (see annotation 5, Figure 3, small vessels were seen on this way (see annotation 6, small probable fishing trawlers on ways (LOA of each roughly 85-90') 		KEY TO NUMBERED ANNOTATIONS ON FIGURE 3
diameter 20') See Figure 6, 3. Possible cylindrical object lying on its transverse axis (diameter is roughly 20'). A total of eight cylindrical objects (two of which were identified as possible submarine hull sections) were visible within the security screen surrounding the submarine building ways in See annotations 4-7, Figure 6, 4. Possible "R" Class SS under construction on building way (exact measurements of the SS cannot be determined - the length of the submarine including the weather sheds at each end is approximately 260'). This submarine appears to be in an advanced stage of construction - the sail appears in place and the deck is painted with a lengthwise dark stripe along the centerline. A small shed is positioned athwartships approximately 45 feet abaft the sail. See annotation 7, 5. Possible tug on building way (LOA approx 100'). It cannot be determined whether this vessel is under construction or repair. This way was formerly used for the construction of an "R" Class SS (see annotation 5, Figure 3, small vessels were seen on this way (see annotation 6, small probable fishing trawlers on ways (LOA of each roughly 85-90')	1.	(visible extent of construction approx 425'). See annotation 10, Probable components for this ship can be
roughly 20'). A total of eight cylindrical objects (two of which were identified as possible submarine hull sections) were visible within the security screen surrounding the submarine building ways in See annotations 4-7, Figure 6, 4. Possible "R" Class SS under construction on building way (exact measurements of the SS cannot be determined - the length of the submarine including the weather sheds at each end is approximately 260'). This submarine appears to be in an advanced stage of construction - the sail appears in place and the deck is painted with a lengthwise dark stripe along the centerline. A small shed is positioned athwartships approximately 45 feet abaft the sail. See annotation 7, 5. Possible tug on building way (LOA approx 100'). It cannot be determined whether this vessel is under construction or repair. This way was formerly used for the construction of an "R" Class SS (see annotation 5, Figure 3, small vessels were seen on this way (see annotation 6, small probable fishing trawlers on ways (LOA of each roughly 85-90')	2.	diameter 20')
ments of the SS cannot be determined - the length of the submarine including the weather sheds at each end is approximately 260'). This submarine appears to be in an advanced stage of construction - the sail appears in place and the deck is painted with a lengthwise dark stripe along the centerline. A small shed is positioned athwartships approximately 45 feet abaft the sail. See annotation 7, 5. Possible tug on building way (LOA approx 100'). It cannot be determined whether this vessel is under construction or repair. This way was formerly used for the construction of an "R" Class SS (see annotation 5, Figure 3, small vessels were seen on this way (see annotation 6, small probable fishing trawlers on ways (LOA of each roughly 85-90')	3.	roughly 20'). A total of eight cylindrical objects (two of which were identified as possible submarine hull sections) were visible within the security screen surrounding the submarine building ways in See annotations
It cannot be determined whether this vessel is under construction or repair. This way was formerly used for the construction of an "R" Class SS (see annotation 5, Figure 3, small vessels were seen on this way (see annotation 6, small vessels were seen on this way (see annotation 6, small probable fishing trawlers on ways (LOA of each roughly 85-90')	4.	ments of the SS cannot be determined - the length of the submarine including the weather sheds at each end is approximately 260'). This submarine appears to be in an advanced stage of construction - the sail appears in place and the deck is painted with a lengthwise dark stripe along the centerline. A small shed is positioned athwartships
	5•	It cannot be determined whether this vessel is under construction or repair. This way was formerly used for the construction of an "R" Class SS (see annotation 5, Figure 3, small vessels
	6.	Four small probable fishing trawlers on ways (LOA of each roughly 85-90') See annotations 7 and 8 below.

	TOP SECRET
	CIA/PIR-77042
	CIA IMAGERY ANALYSIS DIVISION
7.	Small vessel hull sections. Various bow, stern, and superstructure sections can be seen in this area of the shipyard. These sections equate to portions of the vessels seen at annotations 6 above and 8 below.
8.	Four small probable fishing trawlers on ways (LOA of each roughly 85-90'). See annotations 6 and 7 above.
	Probable "R" Class SS alongside camel at offshore wharf (visible waterline length approx 245'). A light-toned triangularly-shaped object appears to extend from the after edge of the sail - this could equate to the snorkel exhaust seen on "R" Class SS. An object possibly equating to the snorkel induction housing of an "R" Class SS can be seen extending from the top of the sail. See annotation 1, Figure 2,
10.	Unidentified probable merchant ship (apparent LOA approx 220').
11.	diameter inside diameter •
12.	Two unidentified, apparently circular, objects - one inside the other. The outside image has a maximum diameter of approximately the inside circle is approximately feet in diameter. These objects appear to be slightly higher, when viewed in stereo, than the adjacent cylindrical object (see annotation 11 above). It cannot be determined if these objects are cylinders.
13.	Three tapered objects, apparently semi-circular in shape, between craneway tracks leading to building way containing a possible "R" Class SS. One of these objects has a "notched-out" section on one side. Similar-looking imagery has been observed at the Wu-chang Shipyard, Wu-chang, China (30-32N 114-17E), in See bottom right caption, Figure 53, CIA/PIR-65038.
	KEY TO FACILITY ANNOTATION ON FIGURE 3
Α.	Transverser system has been extended from the possible turntable to a position in line with the craneway paralleling the down river side of the large building way containing the merchant ship under construction at annotation 1 above. Construction on the tracks and the possible turntable at the head of the craneways does not as yet appear to be completed. See annotation "C", Figure 2,
	- 4 -
	TOP SECRET



_	CIA IMAGERY ANALYSIS DIVISION	CIA/PIR-77042
	REFERENCES	
DOCUMENTS		
CIA/PIR-77009, K	Kiangnan Shipyard, Shanghai, China,	
CIA/PIR-67268, K	TOP SECRET	
CIA/PIR-67221, K	Tiangnan Shipyard, Shanghai, China,	
	Search of Major Chicom Shipyards for truction, September 1965 (TOP SECR	

Approved For Release **TOP**/1**SECRET***T05161A001400010021-1